




# Rolls-Royce

## Volcanic ash implications for aero engines

Frank Haselbach  
23<sup>rd</sup> June 2010



### © Rolls-Royce plc 2010

The information in this document is the property of Rolls-Royce plc and may not be copied or communicated to a third party, or used for any purpose other than that for which it is supplied without the express written consent of Rolls-Royce plc.

This information is given in good faith based upon the latest information available to Rolls-Royce plc, no warranty or representation is given concerning such information, which must not be taken as establishing any contractual or other commitment binding upon Rolls-Royce plc or any of its subsidiary or associated companies.

The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# Outline



- Introduction
- Basic engine operation principles
- Ash ingestion into engines
  - Basic threats
  - Known ash cloud encounters
  - Available test data
- Conclusions and way forward

The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# Introduction



3

- Traditional volcanic ash management was based on exclusion zones around visible volcanic ash plumes (upper picture)
- New methodology emerged (Met-Office Model) which allowed a more numerate prediction with concentration level forecast (lower picture).
- However, this needed OEMs to define acceptable limits and the concentration modelling needs validation
- Engine OEMs initiated risk assessment to support Authorities lifting of restrictions
- Conclusion: At defined low levels of actual concentration in atmosphere:
  - No significant deposits on key components
  - No operational risk arises



The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# How engines work (1)






- Engines burn fuel to convert heat into mechanical (shaft) power to drive a bypass fan
- This heat conversion is more efficient when done at high temperatures and pressures.
- The fan accelerates large amounts of air rearward and thereby generates thrust very efficiently (and quietly)
- A small portion of thrust also comes from the hot jet out of the core engine

The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# How engines work (2)

## Engine cycle




The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# How engines work (3)

Operating principle of a modern jet engine and some key figures

Overall Pressure ratio: ~50




Steel starts to glow red at 700°C

The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.



# What does the ash do in the engine ?





The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# Why Is Operation In Volcanic Ash An Issue ?

- Ash melts in Combustor and deposits in HP Turbine – causing external blockage leading (in extreme) to engine instability and potential flame out
- Erodes compressor blades and liners
- Fine particles can get in to oil system and damage transmissions components
- Pneumatic control items may be sensitive to small particles



Strong NGV contamination  
(BA 9, Jakarta 1982)



The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.



# BA Flight 9 (1982) - Jakarta

On 24 June 1982, the route was flown by the *City of Edinburgh*, a 747-236B. The aircraft flew into a cloud of volcanic ash thrown up by the eruption of Mount Galunggung (circa 180 kilometres (110 mi) south-east of Jakarta, Indonesia), resulting in the failure of all four engines. The reason for the failure was not immediately apparent to the crew or ground control. The aircraft was diverted to Jakarta in the hope that enough engines could be restarted to allow it to land there.

Date	24 June 1982
Type	Flameout of all engines due to blockage by volcanic ash
Site	Mount Galunggung, West Java, Indonesia
Passengers	248
Crew	15
Injuries	0
Fatalities	0
Survivors	263 (all)
Aircraft type	Boeing 747-263B
Aircraft name	<i>City of Edinburgh</i>



The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.


# BA Flight 9 (1982)

pictures of 1 engine which was not re-started

HP NGV leading edge



HP turbine blade leading edge




The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# BA Flight 9 (1982)

**Not-re-started engine**

HP NGV leading edge



**Deposition**

**Re-started engine**

HP NGV L.E. after flying home



**No Deposition**

The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# What testing has been done in the past?

- Whole Engine ash ingestion tests have been conducted at a research laboratory in between 1980 – 1995\*
- A good portion of this data has been openly reported in the literature
- In addition, a US based engine OEM conducted various engine tests with different ‘earth mixes’\*\*
- Engine OEMs have recently shared all relevant data amongst each other for safety purposes

\* Dunn, Baran and Miatech , *ASME J Gas turbines power*, vol.118, 1996 pp 724-731

\*\* private communication

The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# Lab/Engine tests (1)

## ● Testing

- Range of engines with different Overall pressure ratio and turbine entry temperature (TET) tested
- Ash concentration levels ranged from 0.1 to 0.3 g/m<sup>3</sup>
- Engine were tested at idle & high power
- Ash from various sources was ingested

## ● Findings

- All tested engines showed signs of St-Elmo's fire and engine surge when exposed to medium to high levels of ash concentration
- Low power idle (lower TET) test did NOT show any signs of surge
- One engine was damaged severely in tests with highest concentration (HP Blade L/E thermal distress and L/E loss, NGV blockage at high level of T/A reduction + F/C holes blocked, HPC erosion)

The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# Lab/Engine tests (2)

Engine parameters unaffected  
(idle)




Fig. 6 Time history of engine parameters during dust experiments for relatively low turbine inlet temperature




Figure 18. Photograph of nozzle guide vane for first-stage high-pressure turbine. Note removed ash deposits and that the cooling holes near the tip are blocked, whereas those near the hub are still open. The removed deposits are relatively brittle and some of the deposited material can be blown off the surface by rain or after the engine cools down. Evidence of partial material removal from the vane can be seen in Figure 9.

Engine parameters affected  
(higher power)

Higher TET




Fig. 7 Time history of engine parameters during dust experiments for relatively high turbine inlet temperature

Increase in  
compressor  
deliver pressure




Fig. 9 History of burner pressure


Engine parameters are influenced if engine is operated at higher temperature (above idle) – this is caused by assertion of ash on HP Nozzles blocking throat and influencing adversely engine operability

The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.




# HPT Vane; After Dust Exposure

(concentration about  $>2 \times 10^{-1} \text{ g/m}^3$ )  
(exposure around 1 hour)



Material Deposits  
on Vane

# The safe to fly – Chart



The information contained in this document is submitted in confidence and is of the kind contemplated by Sections 41 and 43 of the Freedom of Information Act 2000.

# Conclusions and way forward

- Engine OEMs know what happens if known quantities of ash get inserted into engine
- A series of different engine tests with regards to ash ingestion had been reviewed
- Previous service experience of ash encounters has been analysed to validate the 'safe to fly' chart
  - Met office re-cast plots
  - Intensity of ash ingestion
- Based on the above safe to fly limits for ash concentrations have been agreed between the Engine OEMs. This limit is  $2 \times 10^{-3}$  g/m<sup>3</sup> actual concentration of ash in the atmosphere.
- Remaining uncertainties in ash concentration modelling need to be addressed via joint expert teams (ongoing).